



# DENSIFIER LS

## **HOW TO USE:**

**Surface Prep:** The surface must be clean and dry and free of dirt, oil or other contaminants. Use CitraPro to remove oily contamination and then treat with Super Blue to open the pores and ensure good penetration.

**Application:** *For best results work at temperatures between 45° F and 100° F. Test a small part of the surface for desired results.* New Concrete - Apply with a low pressure sprayer as a single wet coat approximately at 300-400 sq. ft. per gallon. Treated surfaces must stay wet for 15 minutes. Very porous areas may require a second spray during the 15 minute period. Remove any remaining product after 15 minutes by rinsing or squeegee.

## **PRECAUTIONARY STATEMENT:**

Wash hands thoroughly after handling. Wear protective gloves/protective clothing/eye protection/face protection. Take off contaminated clothing and wash before reuse. Dispose of contents/container according to local, state and federal regulations.

## **FIRST AID:**

IF INGESTED: Rinse mouth with water, and drink several glasses of water. Do not induce vomiting. Get Medical Attention.

IF IN EYES: Flush thoroughly with water for 15 minutes, lifting both eyelids. Get Medical Help.

IF ON SKIN: Rinse off thoroughly with soap and water. Wash contaminated clothing before reuse.

INHALATION: Remove to fresh air. Give resuscitation. Get Medical Attention.

## **IN CASE OF FIRE:**

This product is not flammable.

## **FOR EMERGENCY HELP**

24 Hours a Day contact:

INFOTRAC at 1-800-535-5053